

FEBRUARY 25, 2005

582-Y 90 Degree Bolt Pattern Identification



Figure # 1 With 90 Degree Mounting Pads

Torque converter covers that have no markings or have a 90 degree mark do not have the offset mounting lug that has been a typical Chrysler trademark. Chrysler began changing mounting lug configurations in 1996.

Torque converter covers that have a circle in either of the two locations shown in figure number two at the right will have a two degree offset mounting lug.



Figure # 2 Depicts 2 Degree Offset Mounting Pads

For additional information, contact the Customer Service Dept. at Dacco Converters by calling 800-443-2226.

